


**No Outages in October
2025 in the Copper Basin**


September 2025 Copper Basin Outages 3 Outages




■ Animals/birds

■ Trees (non-weather related)

August 2025 Copper Basin Outages 8 Outages




July 2025 Copper Basin Outages 10 Outages




■ Unknown Cause ■ Animals/birds ■ Material or equipment fault/failure ■ Public or Members ■ Construction

**June 2025 Copper Basin Outages
7 Outages**



■ Material or equipment fault/failure ■ Trees (non-weather related)

May 2025 Copper Basin Outages 3 Outages




■ Wind/trees outside ROW

■ Maintenance

■ Unknown Cause

Date	Cause
5/2/2025	Tree on line, removed, closed cutout
5/12/2025	Scheduled outage to replace pole at R63-12
5/19/2025	Unknown reason for open fuse AT G187-5, refused


April 2025 Copper Basin Outages 6 Outages



■ Material or equipment fault/failure
 ■ Animals/birds
 ■ Trees (non-weather related)

Date	Cause
4/2/2025	Squirrel blew cutout, refused
4/9/2025	Replaced dead end bells
4/13/2025	Tree on wire at E5-8, removed tree and closed F2421/31A, outside ROW
4/14/2025	Phase off insulator, replaced insulator
4/16/2025	Down wire span, wire rehung
4/27/2025	Bad elbow on transformer, replaced

March 2025 Copper Basin Outages 8 Outage




■ Material or equipment fault/failure

■ Animals/birds

■ Trees (non-weather related)


■ Unknown Cause

February 2025 Copper Basin Outages
1 Outage



■ Unknown Cause

January 2025 Copper Basin Outages
22 Outages



■ Material or equipment fault/failure
■ Snow/ice/sleet/frost (not trees)
■ Unknown Cause

■ Snow/ice/sleet/frost/trees outside ROW
■ Snow/ice/sleet/frost/trees in ROW