



2012 Glennallen Main Building Remodel--75' 6" x 52' (Approx. 4000 sq ft)

Task	Requirements
New Boiler	Must be compatible with heat loop from power plant
Replace Carpet & Baseboard Trim	Must use EUROTILE: Rhone 7043 02 Graphite (carpet squares) & ROPPE: Cove Base 700 4 CB 4 FT--Blk Brown
Paint Interior & Exterior (All of the paint color numbers are True Value)	Must use color listed below...would like <u>light</u> texturing & semi-gloss paint Interior Colors: Walls-- #12D3 (Palapa), Trim-- #12D6 (Bitter Chocolate) Exterior Colors: Walls-- #06C6 (Mississippi River), Trim-- #14D2 (Amusement)
New Metal Roof/Re-roof Existing	Brown & install snow breaks on both sides
Rebuild Front Porch w/ 2 Exterior Doors	New or remodel, 13' x 6' 2", Ramp & entry steps (wood or metal grating), 42x84 Doors Includes (3) 69 3/4 x 57 picture windows (listed below)...two front windows tinted
Kitchen Floor	Replace with linoleum, 12' x 9'
Install Heat Recovery Ventilation System	with HEPA filters
Board Room Air Conditioner	Wall or window mount
Windows	Replace entire building--(20) 30 x 53, (3) 69 3/4 x 57, (1) 45 3/4 x 57
Install Water Treatment System	Reverse Osmosis--commercial grade
Pave or Chip-Seal Parking Lot & Drainage	Reconfigure drainage of parking lot/front of building area- 122' x 63', 137' x 60'
Rebuild Hallway & Replace 2 Exterior Doors	Rebuild 11' 1" x 7' 2" breezeway that connects main building w/ annex Door is 42 x 79 1/4 (OTHER exterior door located on west side of bldg--same size)
Lighting	Rebalast and relamp all light fixtures to T8s -- (63) 2 x 4, (2) 1 x 4
Exterior Lighting	Install security lighting, i.e. motion, dusk to dawn
New Security System	Turn key, installed, battery backup, entry/exit "logging" capable, panic button features
Bathroom Upgrades	(2) 12' x 8' floors w/linoleum, replace wash basin in mens room, add auto flush to 1 urinal
New Outside Sign	Lighted, CVEA current logo




Existing Breezeway—Need Rebuilt



Kitchen Floor



Existing Entry Porch-Needs Rebuilt or Updated



Front Entry Handicap Ramp



Front View of Entry Porch



Full View of Front of Building



Side View of Building



Boiler—Burnham PF35 – Need Replaced